



TL98813

# TWIN TORCH

Before Initial Use, Fully charge Twin Torch Light for 8 hours. To prevent fire or personal injury, only use adapters and charging base supplied to recharge Twin Torch Light.

Please read through instructions before initial use and keep for future reference.

## CHARGING INSTRUCTIONS:

1. Plug wall adapter into wall outlet (110-120VAC 60Hz).
2. Insert charging plug from wall adapter into charging jack on base. LED indicator light should turn GREEN.
3. Dock the charging end of Twin Torch light into charging base. The Mac Tools logo® should be facing front of charger to allow secure contact. LED indicator light should turn RED.
4. Twin Torch light is fully recharged when LED indicator light turns GREEN.

## OPERATING INSTRUCTIONS:

1. Top button will toggle through lighting sequence as listed below:
  - a. Flashlight head
  - b. UV LED
  - c. Red LED (constant-on)
  - d. Red LED (flashing)
  - e. Light will loop from (a.) through (d.)
2. Bottom button will toggle through lighting sequence as listed below:
  - a. High (all 30 LED)
  - b. Low (top 15 LED)
  - c. Low (bottom 15 LED)
  - d. Light will loop from (a.) through (c.)
3. To turn light off, hold switch button down for 2 seconds.
4. Light will shut off automatically when docked into charging base.

## ACCESSORIES:

To change out an accessory on either end of the Twin Torch light, twist end cap counter-clockwise ¼ turn to release accessory from cap and light body tube. Place desired accessory into groove, then twist end cap clockwise to tighten.