

Release Notes

Version 3.0.1.7

Overview

Version 3.0.1.7 contains major coverage additions and improvements. Also provided are selected highlights of new special tests, fixed issues reported by technicians, and other improvements. You may notice many more in the software that are just too numerous to identify individually. Many thanks for the useful feedback we are receiving. More coverage and enhancements on the way!

New Vehicle Coverage

- Honda New coverage for 2018MY vehicles and systems (Pre/Post Scan + DataStream)
- Subaru New coverage for 2018MY vehicles and systems (Pre/Post Scan + DataStream)
- Jaguar New coverage for 2015-2017MY vehicles and systems (Pre/Post Scan + DataStream)
- Land Rover New coverage for 2015-2017MY vehicles and systems (Pre/Post Scan + DataStream)
- New Systems -1,256
- **New Vehicle-ECU Combinations** 2,026
- New Adjustment type tests 27
- New Actuation type tests 178
- **Updated Diagnostic Information for the following:**
 - Data Item Circuit Description for Honda, Hyundai, Kia, Mazda, Nissan, Toyota
 - o Data Item Operating Ranges for Hyundai, Kia, Mazda, Mitsubishi, Nissan, Toyota
 - ABS Brake Bleed Procedures
 - Tune-Up Specifications

New Coverage – USA Domestic

Chrysler/Jeep Coverage

7 new Adjustment type special tests including:

- **Engine/PCM** Coolant Three Way Valve, Driving Regeneration Request
- **ABS** Steering Angle Calibration
- Others POWER LIFTGATE Close Door Calibration

2 new Actuation type special tests including:

- Engine/PCM Engine Running Injector Kill Test
- Body Control 1st Row Ceiling Light





Updated Diagnostic Information for the following:

- ABS Brake Bleed Procedures
- Tune-Up Specifications

Ford Coverage

3 new Adjustment type special tests including:

Brakes/ABS - Calibrate Longitudinal Acceleration Sensor, Electronic Integrated Park Brake, IVD Sensors Calibration

20 new Actuation type special tests including:

Brakes/ABS - ABS Booster Solenoid Current, Hydraulic Pump Motor, Inlet Valve tests, Outlet Valve tests, TCS Priming Valve tests, On Demand Test

Updated Diagnostic Information for the following:

Tune-Up Specifications

General Motors / Saturn Coverage

Special test fixes/improvements:

- 2015 Camaro PCM improved usage of Injector Kill test
- 2014 Silverado TPMS fixed Tire Pressure Sensor Registration test not available

Other fixes/improvements:

2011 HHR - fixed info missing for Drive Cycle, Battery Resets and Key FOB

Updated Diagnostic Information for the following:

ABS Brake Bleed Procedures

New Coverage – USA Asian

Honda/Acura Coverage

- New coverage for 2018MY vehicles and systems (Pre/Post Scan + DIs)
- Added coverage for 70 new systems
- Added coverage for 517 new vehicle-ecu combinations

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- ABS Brake Bleed Procedures





Hyundai Coverage

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- Data Item Operating Ranges for 2016MY

Kia Coverage

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- Data Item Operating Ranges for 2016MY

Mazda Coverage

Special test fixes/improvements:

2011 Mazda3 AIRBAG - fixed no tests available

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- Data Item Operating Ranges for 2016MY
- ABS Brake Bleed Procedures

Mitsubishi Coverage

1 new Adjustment type special tests including:

Others - OCCUPANT CLASSIFICATION MODULE Zero Calibration and System Test

4 new Actuation type special tests including:

Engine/PCM - A/C Relay, Fuel Pump, Radiator Fan High, Radiator Fan Low

Updated Diagnostic Information for the following:

- Data Item Operating Ranges for 2016MY
- **ABS Brake Bleed Procedures**

Nissan/Infiniti Coverage

2 new Adjustment type special tests including:

- Engine/PCM Fuel Pressure Release
- Climate (HVAC) Blow Set

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- Data Item Operating Ranges for 2016MY
- **ABS Brake Bleed Procedures**







Subaru Coverage

- New coverage for 2018MY vehicles and systems (Pre/Post Scan + DIs)
- Added coverage for 74 new systems
- Added coverage for 184 new vehicle-ecu combinations

6 new Adjustment type special tests including:

- Transmission Clear AT learning mode
- ABS ABS Sequence Control Mode, Brake Lamp Lighting Operation, RAB Operation Record Data, VDC Function Check Mode, VSC(VDC) Centering Mode

150 new Actuation type special tests including:

- Engine/PCM A/C Compressor Relay, Active Grill Shutter Test, CPC Solenoid Valve, ELCM pump, ELCM switching valve, Fuel Pump Control-off drive, Fuel Pump Relay, Injection Stop Mode tests, Radiator Fan Relay
- Instrument Cluster/Meter Range Display tests, Lamp and Indicator tests, Gauge tests
- Climate (HVAC) A/C Change Setting, Air Mix Door Actuator Target Open (Driver Side), Ambient Air Temperature setting, AUTO switch mode setting, Blower Fan Level Setting, Fresh/Rec Air Dr Act Trgt Open Angle, Heater Water Temperature Setting, In-Vehicle Air Temperature Setting, Mode Door Actuator Opening Angle Target, Quantity of Sunload Setting, Rear Defogger
- Others tests for KEYLESS ACCESS WITH PUSH START, MULTI FUNCTION DISPLAY, BLIND SPOT/CROSS TRAFFIC, TELEMATICS

Toyota/Lexus Coverage

Updated Diagnostic Information for the following:

- Data Item Circuit Description for 2016MY
- Data Item Operating Ranges for 2016MY
- **ABS Brake Bleed Procedures**

New Coverage – USA European

Alfa Romeo Coverage

1 new Adjustment type special tests including:

ABS - Steering Angle Calibration

Fiat Coverage

1 new Adjustment type special tests including:

ABS - Steering Angle Calibration



Jaguar Coverage

- New coverage for 2015-2017MY vehicles and systems (Pre/Post Scan + DIs)
- Added coverage for 455 new systems
- Added coverage for 668 new vehicle-ecu combinations

Land Rover Coverage

- New coverage for 2015-2017MY vehicles and systems (Pre/Post Scan + DIs)
- Added coverage for 657 new systems
- Added coverage for 657 new vehicle-ecu combinations

Mercedes Benz

1 new Adjustment type special tests including:

• **Steering** – EPS Reset Learned Values

Volvo

Special test fixes/improvements:

• 2010 S80 PARKING BRAKE - fixed Caliper Release test not working properly



